


External Feedback to Pilot

For specific information please refer to the Swagelok Process Regulators, Pressure Reducing, User Manual, MS-CRD-0290. QR-Code to instructions:



Caution: The outlet pressure must be fed back to the external feedback connection. Failure to do so may result in damage and non-functioning of the regulator.



Swagelok

swagelok.com

©2026 Swagelok Company

MS-CRD-0310, Rev- February 2026